



Bremszylinder für BT 1958-72 und ServiCar 1951-73 Hinterräder

4036-M1	BT 1958-62, Wagner,	OEM 41740-58
4036-M2	BT 1963-72, Wagner,	OEM 41740-63
4036-M3	ServiCar 1951-73, Accel,	OEM 83460-51

Überhol-Kits

4036-M7	BT 1958-62, Wagner,	OEM 41748-58
4036-M8	BT 1963-72, Wagner,	OEM 41748-63
4036M9	Servi Car 1951-73,	OEM 83462-51



Anschlüsse für Bremsleitungen an 1958-72 Trommelbremsen hinten

4036-M15	BT 1958-62, OEM 41745-58
4036-M16	BT 1963-72, OEM 41750-63
4036-M20	Dichtring für Anschluß, BT 1958-72, OEM 41744-58



Remote Hauptbremszylinder

MM4366A ersetzt OEM 42446-87B